

AffinityWater

Barn Meadows and Pondwicks Meadow

River Restoration Construction
Photographs



Tree Works



**Feb 2023 – Willow Pollarding
(& tree removal)**



July 2023 – Willow Growth

Gravel Augmentation



Before – heavy silt deposition caused by low flows



After – clear gravels



Before – straight silted channel

Earth berms

Small meanders



After – small meanders

Earth
berm

AffinityWater

Low and High Flow Channel



Before - channel during medium-high flows



Low flow channel

During – low flow channel

Backwaters at Pondwicks

Before



During



After



Backwaters at Pondwicks – when will they be wet and dry?

